

ALLIANCE RESOURCE PARTNERS LP
Form 8-K
May 16, 2011

UNITED STATES
SECURITIES AND EXCHANGE COMMISSION

WASHINGTON, DC 20549

FORM 8-K

CURRENT REPORT

PURSUANT TO SECTION 13 OR 15(d) OF THE
SECURITIES EXCHANGE ACT OF 1934

Date of report (Date of earliest event reported): May 10, 2011

ALLIANCE RESOURCE PARTNERS, L.P.

(Exact name of registrant as specified in its charter)

Delaware
(State or other jurisdiction of
incorporation or organization)

0-26823
Commission
File No.:

73-1564280
(IRS Employer
Identification No.)

Edgar Filing: ALLIANCE RESOURCE PARTNERS LP - Form 8-K

1717 South Boulder Avenue, Suite 400, Tulsa, Oklahoma 74119

(Address of principal executive offices and zip code)

(918) 295-7600

(Registrant's telephone number, including area code)

Check the appropriate box below if the Form 8-K filing is intended to simultaneously satisfy the filing obligations of the registrant under any of the following provisions:

- .. Written communications pursuant to Rule 425 under the Securities Act (17 CFR 230.425)
- .. Soliciting material pursuant to Rule 14a-12 under the Exchange Act (17 CFR 240.14a-12)
- .. Pre-commencement communications pursuant to Rule 14d-2(b) under the Exchange Act (17 CFR 240.14d-2(b))
- .. Pre-commencement communications pursuant to Rule 13e-4(c) under the Exchange Act (17 CFR 240.13e-4(c))

ITEM 8.01 Other Events

On July 21, 2010, the Dodd-Frank Wall Street Reform and Consumer Protection Act (the Act) was enacted. Section 1503 of the Act included new reporting requirements related to mine safety, including disclosing on a Current Report on Form 8-K the receipt of an imminent danger order under Section 107 (a) of the Federal Mine Safety and Health Act of 1977 (the Mine Act) issued by the Federal Mine Safety and Health Administration (MSHA).

On Tuesday, May 10, 2011, Warrior Coal, LLC (Warrior), an operating subsidiary of the Partnership, was issued an imminent danger order under Section 107(a) of the Mine Act. The order was issued after an MSHA coal mine inspector alleged that a portion of the mine wall, or rib, was loose near the general vicinity of a roof bolting machine of the mine's #2 Unit. Warrior disputes the MSHA inspector's findings, including his description of the coal rib as loose and his allegation that the rib constituted an imminent danger. Warrior intends to seek judicial review of the order's issuance.

SIGNATURES

Pursuant to the requirements of the Securities Exchange Act of 1934, the Registrant has duly caused this report to be signed on its behalf by the undersigned, thereunto duly authorized.

Alliance Resource Partners, L.P.

By: Alliance Resource Management GP, LLC,
its managing general partner

By: /s/ Joseph W. Craft III
Joseph W. Craft III
President and Chief Executive Officer

Date: May 16, 2011