

HARMONY GOLD MINING CO LTD

Form 6-K

February 06, 2014

UNITED STATES

SECURITIES AND EXCHANGE COMMISSION

Washington, D.C. 20549

Form 6-K

REPORT OF FOREIGN PRIVATE ISSUER PURSUANT TO
RULE 13a-16 OR 15d-16 UNDER THE SECURITIES
EXCHANGE ACT OF 1934

For 06 February 2014

**Harmony Gold Mining Company
Limited**

Randfontein Office Park

Corner Main Reef Road and Ward Avenue

Randfontein, 1759

South Africa

(Address of principal executive offices)

(Indicate by check mark whether the registrant files or will file annual reports under cover of Form 20-F or Form 40-F.)

Form 20-F Form 40-F

(Indicate by check mark whether the registrant by
furnishing the information contained in this form
is also thereby furnishing the information to the
Commission pursuant to Rule 12g3-2(b) under the
Securities Exchange Act of 1934.)

Yes No

**Issued by Harmony Gold
Mining Company Limited
6 January 2014**

**For more details contact:
Russell and Associates
Charmane Russell and/or
James Duncan**

**Tel:
+27 (0)11 880 3924**

**James Duncan mobile:
+27 (0) 82 318 9855**

**Charmane Russell mobile:
+27 (0) 82 372 5816**

**Corporate Office:
Randfontein Office Park
P O Box 2
Randfontein
South Africa 1760**

**T
+27 (11) 411 2000**

www.harmony.co.za

JSE: HAR

NYSE: HMY

ISIN No.: ZAE000015228

**Registration number:
1950/038232/06**

Sponsor:

**J.P. Morgan Equities South
Africa Proprietary Limited
Update 3: Doornkop mine**

Johannesburg: Thursday, 6 February 2014: Harmony Gold Mining Company Limited (“Harmony” and/or “the company”) regrets to advise that rescue workers have located the bodies of eight of the employees who were unaccounted following the fire at the Doornkop gold mine. The search continues for the ninth employee.

The fire was reported in a stope adjacent to 192 level haulage (some 1 733m underground) around 18:00 on Tuesday, 4 February 2014, following a seismic event that triggered a fall of ground. Rescue teams were immediately dispatched underground, but access to the affected area was hampered by smoke and a fall of ground.

At around 07:00 on 5 February, rescue workers located eight employees in an underground refuge chamber, and they were brought to surface, unharmed, by 11:00. Harmony’s CEO Graham Briggs, the board and management extend their condolences to the families, friends and colleagues of the men who died.
end.

SIGNATURES

Pursuant to the requirements of the Securities Exchange Act of 1934, the registrant has duly caused this report to be signed on its behalf by the undersigned, thereunto duly authorized.

Dated: 06, February 2014

Harmony Gold Mining Company Limited

By:

/s/ Frank abbott

Name: Frank abbott

Title: Financial Director